



## ASBESTOS RE-INSPECTION SURVEY REPORT

GENERAL SERVICES ADMINISTRATION  
REGION 10  
SAFETY AND ENVIRONMENTAL TEAM  
400 15<sup>th</sup> STREET SW  
AUBURN, WA 98001



CONDUCTED AT:

WAREHOUSE 2  
GSA BUILDING NUMBER WA0825KF  
2703 C STREET SW  
AUBURN, WASHINGTON

ASSESSMENT DATE:  
09-14- 2012

PREPARED BY:  
UNITED STATES PUBLIC HEALTH SERVICE  
FEDERAL OCCUPATIONAL HEALTH SERVICE  
DALLAS AREA OFFICE  
1301 YOUNG STREET, SUITE 772  
DALLAS, TX 75202



## RE-INSPECTION PROJECT SCOPE

At the request of General Services Administration (GSA), Med-Tox Northwest (MTNW), representing U.S. Public Health Service Federal Occupational Health (FOH), performed a condition re-inspection of GSA's Warehouse 2 (building number WA0825KF) located at 2703 C Street Southwest in Auburn, Washington. A visual inspection was conducted and provided a current physical assessment of previously identified asbestos-containing building materials (ACBM) and materials that were assumed asbestos-containing as identified in the March 29, 2007 EHS International, Inc. (EHSI) re-inspection report. Physical assessment data from the 2007 EHSI report was also reviewed. Material location drawings can be found in Appendix A. Copies of the current physical assessment data sheets (Asbestos Re-inspection forms) can be found in Appendix B. This re-inspection of GSA's Warehouse 2 was performed on September 14, 2012 by FOH representative Marc Rickert of MTNW, a certified Asbestos Hazard Emergency Response Act (AHERA) building inspector. Mr. Rickert's AHERA building inspector certification is included in Appendix C.

## BUILDING DESCRIPTION

GSA's Warehouse 2 is primarily a warehouse building with shop and office areas. Interior finishes include exposed wood framing, plaster, gypsum wallboard and acoustical ceiling tile, carpet and vinyl floor tile. The structure is wood-framed with a flat built-up roof. Heating is provided by a hydronic system.

## ASBESTOS CONTAINING MATERIALS PREVIOUSLY IDENTIFIED

As part of the scope of this re-inspection, the 2007 EHSI re-inspection report for GSA's Warehouse 2 was reviewed. This GSA facility does contain known friable and non-friable ACM. The following table provides a summary of asbestos materials identified from the 2007 EHSI re-inspection report:

Material	Location	Quantity	Abatement estimate
Pipe insulation	Throughout (except boiler room)	2,260 linear feet	\$20.00 linear foot
Pipe fittings	Throughout (except boiler room)	530 each	\$25.00 each
Floor expansion seam caulking	Warehouse bays 1-4	1,480 linear feet	\$6.00 linear foot
Ductwork insulation	Back room of 207 and office roof	560 square feet	\$12.00 square foot

<b>Material</b>	<b>Location</b>	<b>Quantity</b>	<b>Abatement estimate</b>
Vibration dampening cloth	Throughout on HVAC system	24 square feet (unknown "each" quantity)	\$150.00 each
9-x 9-inch vinyl asbestos tile (VAT) and ACM mastic on concrete	Offices, hallway, electronic shop, 205, 207, 209, entry to restrooms	3,156 square feet	\$2.00 square foot
Cement asbestos board	Exterior and sprinkler control housings	3,800 square feet	\$1.65 square foot
Asphalt roofing felts and tar*	Roof	Unknown	\$1.50 square foot
Black Countertop	Electronics shop, rooms 205 and 207	560 square feet	\$1.50 square foot
Exterior wall expansion joints	Exterior walls	1,400 linear feet	\$6.00 linear foot

\*Material listed in EHSI 2007 re-inspection report's Executive summary but not found in assessment data sheets.

Note: Unit pricing could be much higher or lower based on the quantity of material that an abatement contractor is bidding on.

Suspect ACM may not have been previously sampled; therefore, was identified as assumed ACM. The following table identifies assumed suspect ACM from the 2007 EHSI re-inspection report:

<b>Material</b>	<b>Location</b>	<b>Quantity</b>	<b>Abatement estimate</b>
Gaskets	Throughout	8 each	\$20.00 each
TSI inaccessible in Boiler room walls	Boiler room walls	Unknown	\$20.00 linear foot
Fire door cores	Throughout	14 each	\$150.00 each
White patching on ceiling joists	Warehouse bays 1-4	200 square feet	\$25.00 square foot

<b>Material</b>	<b>Location</b>	<b>Quantity</b>	<b>Abatement estimate</b>
Gaskets	Throughout	8 each	\$20.00 each
TSI inaccessible in Boiler room walls	Boiler room walls	Unknown	\$20.00 linear foot
Fire door cores	Throughout	14 each	\$150.00 each
White patching on ceiling joists	Warehouse bays 1-4	200 square feet	\$25.00 square foot
Felt vapor barrier under CAB in exterior soffit	Exterior and sprinkler control housings	3,800 square feet	\$0.50 square foot

Note: Unit pricing could be much higher or lower based on the quantity of material that an abatement contractor is bidding on.

Suspect materials that were previously sampled and found to be non-asbestos containing as identified in the 2007 EHSI re-inspection report are identified in the following table:

<b>Material</b>	<b>Location</b>
Gypsum wallboard system	Office area and fitness area
Window putty	Throughout
Carpet mastic	Office area fitness area and hallway
Cove base and mastic	Throughout
2- x 2-foot blue tread vinyl floor tile and mastic	Men and Women's locker rooms
12-x 12-inch vinyl floor tile and mastic	Men and Women's locker rooms
Duct seam sealant	Throughout
2-x 4-foot suspended acoustic ceiling tile	Throughout
Plaster	Ceilings and wall throughout office areas
Terra cotta wall grout and mortar	Exterior walls
Exit door interior insulation	Office 213 north wall



For a complete listing of the current re-inspection assessment forms, see Appendix B.

## **RE-INSPECTION OBSERVATIONS**

All previously identified asbestos containing materials appear to be in good to fair condition at the time of the re-inspection.

## **CONCLUSIONS AND RECOMMENDATIONS**

The material condition should be monitored by all employees in the facility, and if any damage is identified, notification must be made to the appropriate individuals.

Based on our conclusions, FOH is making the following recommendations: Continue to monitor material condition-any damage must be repaired or cleaned by asbestos certified workers. At a minimum, asbestos awareness training should be provided to all maintenance workers as required by Federal and State regulations.

If any remodeling or demolition is to be performed, FOH recommends that a destructive inspection be performed. Destructive sampling would identify any concealed materials that may be disturbed by the project and potentially exclude materials that are presently known or assumed asbestos. Federal and State regulations require that any suspect material be treated as asbestos-containing until laboratory analysis demonstrates that it is non-asbestos. This sampling must be conducted by an accredited EPA/AHERA building inspector. The analysis must be performed by an accredited laboratory.

A copy of FOH representative Marc Rickert's AHERA building inspector certification is included in Appendix C.

## **LIMITATIONS**

Reasonable effort was made by FOH to locate and reassess the condition of all materials identified in the EHSI re-inspection. During the current re-inspection, not all rooms or areas were accessible due to tenant restrictions. As part of this re-inspection, GSA should note that only materials defined as being suspect materials in the EHSI re-inspection were to be assessed during this re-inspection, and did not require the addressing of concealed materials within the building. The scope of work did not include verification of the original survey documents. While the assessment of these materials is not required, sampling of these materials is required by local and/or State of Washington regulations prior to renovations or demolition of a building. Destructive investigation and sampling is required prior to any renovation or demolition of the building. Failure to follow these recommendations may result in visible emissions of unknown asbestos materials resulting in regulatory citations and monetary fines; FOH cannot be held liable or responsible for failure to follow these recommendations.

This report has been prepared for the exclusive use of FOH and GSA; FOH cannot be held responsible for interpretation by others of the data contained in this report; any use of this report shall include the entire document. This re-inspection is not intended for use as abatement plans, specifications or abatement project design.

If you have any questions regarding this report or require further clarification, please do not hesitate to contact me at (253) 351-0677.

Inspected By:

A handwritten signature in black ink, appearing to read "Marc Rickert". The signature is fluid and cursive, with a long horizontal stroke at the end.

Marc Rickert

AHERA Asbestos Building Inspector Certification #:13-BI-2501

Expires: 5/17/2013

Reviewed By:

A handwritten signature in blue ink, appearing to read "Ingrid M. Holznagel". The signature is cursive and somewhat stylized.

Ingrid Holznagel

Project Manager

Attachments:

Appendix A – Drawings

Appendix B – Asbestos Re-inspection Forms

Appendix C – AHERA Building Inspector Certification

## **APPENDIX A**

## **DRAWINGS**





## BUILDING NOTES



1. DRAWING IS SCHEMATIC AND MATERIAL LOCATIONS FOR ASBESTOS ARE APPROXIMATE.
2. REFER TO REPORT FOR MORE INFORMATION ABOUT THE SAMPLED OR ASSUMED MATERIALS.
3. CONCEALED AND ACCESSIBLE PIPING INSULATION ON DOMESTIC AND HYDRONIC PIPING IS ASBESTOS CONTAINING.
4. JOINT COMPOUND IN THIS BUILDING TESTED <1% (LESS THAN 1%) ASBESTOS. WA STATE DEPARTMENT OF LABOR AND INDUSTRIES (L&I) PER WISHA REGIONAL DIRECTIVE 23.30 DATED 12/28/2000. REQUIRES DEMOLITION PERSONNEL TO BE TRAINED IN ACCORDANCE WITH WAC. 296-62-0772215.
5. IN ADDITION TO THE ASBESTOS CONTAINING MATERIALS SHOWN ON THIS DRAWING, THE FOLLOWING ITEMS HAVE BEEN CONFIRMED OR ARE ASSUMED TO CONTAIN ASBESTOS:
  - A. ACM EXPANSION JOINTS ON EXTERIOR WAREHOUSE WALLS
  - B. DUCTWORK INSULATION
  - C. VIBRATION DAMPENING CLOTHS
  - D. GASKETS
  - E. FLOOR EXPANSION SEAM CAULKING
  - F. PATCHING ON WOOD JOIST BEAM AT CEILING LEVEL

## SHEET NOTES

- ① ASBESTOS CONTAINING CORE FIREDOOR
- ② BLACK ASBESTOS CONTAINING COUNTERTOP
- ③ VINYL ASBESTOS TILE WITH ASBESTOS CONTAINING MASTIC
- ④ CARPET OVER VINYL ASBESTOS TILE WITH ASBESTOS CONTAINING MASTIC

## LEGEND

-  ACM-CORE FIREDOOR
-  BLACK ACM COUNTERTOP
-  VAT AND ACM MASTIC
-  CARPET OVER VAT AND ACM MASTIC



KEY PLAN




## BUILDING NOTES



1. DRAWING IS SCHEMATIC AND MATERIAL LOCATIONS FOR ASBESTOS ARE APPROXIMATE.
2. REFER TO REPORT FOR MORE INFORMATION ABOUT THE SAMPLED OR ASSUMED MATERIALS.
3. CONCEALED AND ACCESSIBLE PIPING INSULATION ON DOMESTIC AND HYDRONIC PIPING IS ASBESTOS CONTAINING.
4. JOINT COMPOUND IN THIS BUILDING TESTED <1% (LESS THAN 1%) ASBESTOS. WA STATE DEPARTMENT OF LABOR AND INDUSTRIES (L&I) PER WISHA REGIONAL DIRECTIVE 23.30 DATED 12/28/2000. REQUIRES DEMOLITION PERSONNEL TO BE TRAINED IN ACCORDANCE WITH WAC. 296-62-0772215.
5. IN ADDITION TO THE ASBESTOS CONTAINING MATERIALS SHOWN ON THIS DRAWING, THE FOLLOWING ITEMS HAVE BEEN CONFIRMED OR ARE ASSUMED TO CONTAIN ASBESTOS:
  - A. ACM EXPANSION JOINTS ON EXTERIOR WAREHOUSE WALLS
  - B. DUCTWORK INSULATION
  - C. VIBRATION DAMPENING CLOTHS
  - D. GASKETS
  - E. FLOOR EXPANSION SEAM CAULKING
  - F. PATCHING ON WOOD JOIST BEAM AT CEILING LEVEL

## SHEET NOTES

- ① ASBESTOS CONTAINING TSI PIPING (INCLUDES FITTINGS)

## LEGEND

 TSI PIPING



KEY PLAN



PROJECT NORTH



**ehsi**  
EHS-International, Inc.  
13228 NE 20th Street, Suite 100  
Bellevue, Washington 98005  
Ph: (425) 452-2959  
Fax: (425) 648-7247

GSA - WAREHOUSE 2  
BUILDING NUMBER - WA0825KF  
AUBURN, WASHINGTON  
HOMOGENEOUS MATERIAL DRAWING

PROJECT MANAGER:  
J. O'MALLEY  
INSPECTORS:  
E. HUARTE  
L. KOLLASCH  
C. ALVAREZ  
SURVEY DATE: 3/14/07  
DHS PROJECT #: 9143-03  
DRAWN BY: ERA  
SCALE: NTS  
ISSUE DATE:

OFFICE AREA  
FLOOR PLAN

HM - 2.0

## BUILDING NOTES

1. DRAWING IS SCHEMATIC AND MATERIAL LOCATIONS FOR ASBESTOS ARE APPROXIMATE.
2. REFER TO REPORT FOR MORE INFORMATION ABOUT THE SAMPLED OR ASSUMED MATERIALS.
3. CONCEALED AND ACCESSIBLE PIPING INSULATION ON DOMESTIC AND HYDRONIC PIPING IS ASBESTOS CONTAINING.
4. JOINT COMPOUND IN THIS BUILDING TESTED <1% (LESS THAN 1%) ASBESTOS. WA STATE DEPARTMENT OF LABOR AND INDUSTRIES (L&I) PER WISHA REGIONAL DIRECTIVE 23.30 DATED 12/28/2000. REQUIRES DEMOLITION PERSONNEL TO BE TRAINED IN ACCORDANCE WITH WAC. 296-62-0772215.
5. IN ADDITION TO THE ASBESTOS CONTAINING MATERIALS SHOWN ON THIS DRAWING, THE FOLLOWING ITEMS HAVE BEEN CONFIRMED OR ARE ASSUMED TO CONTAIN ASBESTOS:
  - A. ACM EXPANSION JOINTS ON EXTERIOR WAREHOUSE WALLS
  - B. DUCTWORK INSULATION
  - C. VIBRATION DAMPENING CLOTHS
  - D. GASKETS
  - E. FLOOR EXPANSION SEAM CAULKING
  - F. PATCHING ON WOOD JOIST BEAM AT CEILING LEVEL



## SHEET NOTES

- ① ASBESTOS CONTAINING CORE FIRE DOORS. INTERNAL FIRE DOORS SEPERATE BAYS AND ARE APPROXIMATELY 10' X 20' EACH.
- ② ASBESTOS CONTAINING TSI PIPING (INCLUDES FITTINGS)
- ③ CEMENT ASBESTOS BOARD ON EXTERIOR SOFFIT AND ASSUMED ASSOCIATED FELT VAPOR BARRIER PAPER
- ④ CEMENT ASBESTOS BOARD ON INTERIOR WALL PANEL LINING OF SPRINKLER CONTROL HOUSINGS

## LEGEND

- ACM-CORE FIREDOORS
- ▨ TSI PIPING

③ ④ TYP. BLDG.



KEY PLAN



## **APPENDIX B**

### **ASBESTOS RE-INSPECTION FORMS**

# AHERA ASBESTOS RE-INSPECTION

## Physical Assessment Data

Building Name:	GSA Warehouse 2	Building Number:	WA0825KF
Service Center:	Northwest/Arctic Region		
Property Manager:	Michelle Leach	Telephone:	253-931-7289
Address:	2703 - C Street Southwest, Auburn, Washington		
HSA #:	216A		
Functional Area / Location:	Floor 1 and roof: Exterior roof soffit, Interior walls of sprinkler control valve housings on west and east walls.		

### ORIGINAL AHERA INSPECTION DATA

Type of Asbestos Material:	<input type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input checked="" type="checkbox"/> Misc.	<input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable	<input type="checkbox"/> Not Accessible
Asbestos Material Description:	Cement asbestos board		
	<input type="checkbox"/> Assumed ACM <input checked="" type="checkbox"/> Laboratory Analysis	ACM %:	Quantity: 3,800 <input checked="" type="checkbox"/> SF <input type="checkbox"/> LF <input type="checkbox"/> EA

### RE-INSPECTION DATA

Date:	9/14/12	Change from Prior Inspection:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Sample Taken:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Amount of Asbestos Material:	3800		<input checked="" type="checkbox"/> SF <input type="checkbox"/> LF <input type="checkbox"/> EA	<input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable	
Asbestos Material Description:	CAB SIDING				

### CONDITION AT THE TIME OF INSPECTION

Type of Damage:	<input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input checked="" type="checkbox"/> Physical	Location of Damage:	<input type="checkbox"/> Localized <input checked="" type="checkbox"/> Distributed
Extent of Damage:	<input type="checkbox"/> 0% <input checked="" type="checkbox"/> 1 - 10% <input type="checkbox"/> 10 - 20% <input type="checkbox"/> > 25%	Overall Rating:	<input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor
Damage Description:			

### POTENTIAL FOR DISTURBANCE

	High	Medium	Low
Contact Frequency:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vibration Influence:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Air Erosion Potential:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Overall Rating:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments: \_\_\_\_\_

Inspector Signature:

*Mark Robert*

Date

*9/14/12*

AHERA Inspector Certification #:

*13-BI-2501*



# AHERA ASBESTOS RE-INSPECTION

## Physical Assessment Data

Building Name:	GSA Warehouse 2	Building Number:	WA0825KF
Service Center:	Northwest/Arctic Region		
Property Manager:	Michelle Leach	Telephone:	253-931-7289
Address:	2703 - C Street Southwest, Auburn, Washington		
HSA #:	216B		
Functional Area / Location:	Floor 1 and roof: Exterior roof soffit		

### ORIGINAL AHERA INSPECTION DATA

Type of Asbestos Material:	<input type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input checked="" type="checkbox"/> Misc.	<input checked="" type="checkbox"/> Friable <input type="checkbox"/> Non Friable	<input type="checkbox"/> Not Accessible
Asbestos Material Description:	Felt vapor barrier paper associated with cement asbestos board		
	<input checked="" type="checkbox"/> Assumed ACM <input type="checkbox"/> Laboratory Analysis	ACM %:	N/A
	Quantity:	1,200	<input checked="" type="checkbox"/> SF <input type="checkbox"/> LF <input type="checkbox"/> EA

### RE-INSPECTION DATA

Date:	9/14/12	Change from Prior Inspection:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Sample Taken:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Amount of Asbestos Material:	1200	<input checked="" type="checkbox"/> SF <input type="checkbox"/> LF <input type="checkbox"/> EA	<input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable		
Asbestos Material Description:	FELT VAPOR BARRIER UNDER SIDING				

### CONDITION AT THE TIME OF INSPECTION

Type of Damage:	<input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input checked="" type="checkbox"/> Physical	Location of Damage:	<input type="checkbox"/> Localized <input checked="" type="checkbox"/> Distributed
Extent of Damage:	<input type="checkbox"/> 0% <input checked="" type="checkbox"/> 1 - 10% <input type="checkbox"/> 10 - 20% <input type="checkbox"/> > 25%	Overall Rating:	<input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor
Damage Description:			

### POTENTIAL FOR DISTURBANCE

	High	Medium	Low
Contact Frequency:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vibration Influence:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Air Erosion Potential:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Overall Rating:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments:			

Inspector Signature:

*Marcus Rickert*

Date

9/14/12

AHERA Inspector Certification #:

13-BI-2501

# AHERA ASBESTOS RE-INSPECTION

## Physical Assessment Data

Building Name:	GSA Warehouse 2	Building Number:	WA0825KF
Service Center:	Northwest/Arctic Region		
Property Manager:	Michelle Leach	Telephone:	253-931-7289
Address:	2703 - C Street Southwest, Auburn, Washington		
HSA #:	245		
Functional Area / Location:	Floor 1 and roof: HVAC room in 207 and Office roof		

### ORIGINAL AHERA INSPECTION DATA

Type of Asbestos Material:	<input type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input checked="" type="checkbox"/> Misc.	<input checked="" type="checkbox"/> Friable <input type="checkbox"/> Non Friable	<input type="checkbox"/> Not Accessible
Asbestos Material Description:	Ductwork insulation		
	<input type="checkbox"/> Assumed ACM <input checked="" type="checkbox"/> Laboratory Analysis	ACM %:	Quantity: 560 <input checked="" type="checkbox"/> SF <input type="checkbox"/> LF <input type="checkbox"/> EA

### RE-INSPECTION DATA

Date:	9/14/12	Change from Prior Inspection:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Sample Taken:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Amount of Asbestos Material:	560		<input checked="" type="checkbox"/> SF <input type="checkbox"/> LF <input type="checkbox"/> EA	<input checked="" type="checkbox"/> Friable <input type="checkbox"/> Non Friable	
Asbestos Material Description:	DUCTWORK INSULATION				

### CONDITION AT THE TIME OF INSPECTION

Type of Damage:	<input checked="" type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical	Location of Damage:	<input type="checkbox"/> Localized <input checked="" type="checkbox"/> Distributed
Extent of Damage:	<input type="checkbox"/> 0% <input checked="" type="checkbox"/> 1 - 10% <input type="checkbox"/> 10 - 20% <input type="checkbox"/> > 25%	Overall Rating:	<input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor
Damage Description:			

### POTENTIAL FOR DISTURBANCE

	High	Medium	Low
Contact Frequency:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Vibration Influence:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Air Erosion Potential:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Overall Rating:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

Inspector Signature:

*Marie J. Pichard*

Date

9/14/12

AHERA Inspector Certification #:

13-BI-2501

# AHERA ASBESTOS RE-INSPECTION

## Physical Assessment Data

Building Name:	GSA Warehouse 2	Building Number:	WA0825KF
Service Center:	Northwest/Arctic Region		
Property Manager:	Michelle Leach	Telephone:	253-931-7289
Address:	2703 – C Street Southwest, Auburn, Washington		
HSA #:	255		
Functional Area / Location:	Floor 1: Throughout, All Exterior Walls		

### ORIGINAL AHERA INSPECTION DATA

Type of Asbestos Material:	<input type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input checked="" type="checkbox"/> Misc.	<input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable	<input type="checkbox"/> Not Accessible
Asbestos Material Description:	Exterior ACM expansion joints		
	<input type="checkbox"/> Assumed ACM <input checked="" type="checkbox"/> Laboratory Analysis	ACM %:	Quantity: 1,400 <input type="checkbox"/> SF <input checked="" type="checkbox"/> LF <input type="checkbox"/> EA

### RE-INSPECTION DATA

Date:	9/14/12	Change from Prior Inspection:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Sample Taken:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Amount of Asbestos Material:	1400		<input checked="" type="checkbox"/> SF <input type="checkbox"/> LF <input type="checkbox"/> EA		<input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable
Asbestos Material Description:	EXTERIOR ACM EXPANSION JOINTS				

### CONDITION AT THE TIME OF INSPECTION

Type of Damage:	<input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical	Location of Damage:	<input type="checkbox"/> Localized <input type="checkbox"/> Distributed
Extent of Damage:	<input checked="" type="checkbox"/> 0% <input type="checkbox"/> 1 – 10% <input type="checkbox"/> 10 – 20% <input type="checkbox"/> > 25%	Overall Rating:	<input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor
Damage Description:			

### POTENTIAL FOR DISTURBANCE

	High	Medium	Low
Contact Frequency:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vibration Influence:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Air Erosion Potential:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Overall Rating:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

Inspector Signature:

*Man A. Rickett*

Date

*9/14/12*

AHERA Inspector Certification #:

*13-BI-2501*

# AHERA ASBESTOS RE-INSPECTION

## Physical Assessment Data

Building Name:	GSA Warehouse 2	Building Number:	WA0825KF
Service Center:	Northwest/Arctic Region		
Property Manager:	Michelle Leach	Telephone:	253-931-7289
Address:	2703 - C Street Southwest, Auburn, Washington		
HSA #:	258		
Functional Area / Location:	Floor 1: Throughout warehouse, Office area hallway - See HM drawings		

### ORIGINAL AHERA INSPECTION DATA

Type of Asbestos Material:	<input type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input checked="" type="checkbox"/> Misc.	<input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable	<input type="checkbox"/> Not Accessible
Asbestos Material Description:	Core Fire doors		
	<input checked="" type="checkbox"/> Assumed ACM <input type="checkbox"/> Laboratory Analysis	ACM %:	N/A
	Quantity:	12 (10' x 20')	2 (3' x 8')
		<input type="checkbox"/> SF <input type="checkbox"/> LF <input checked="" type="checkbox"/> EA	

### RE-INSPECTION DATA

Date:	9/14/12	Change from Prior Inspection:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Sample Taken:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Amount of Asbestos Material:	12 (10x20) 2 (3x8)		<input type="checkbox"/> SF <input type="checkbox"/> LF <input checked="" type="checkbox"/> EA		<input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable
Asbestos Material Description:	CORE FIRE DOOR				

### CONDITION AT THE TIME OF INSPECTION

Type of Damage:	<input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical	Location of Damage:	<input type="checkbox"/> Localized <input type="checkbox"/> Distributed
Extent of Damage:	<input checked="" type="checkbox"/> 0% <input type="checkbox"/> 1 - 10% <input type="checkbox"/> 10 - 20% <input type="checkbox"/> > 25%	Overall Rating:	<input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor
Damage Description:			

### POTENTIAL FOR DISTURBANCE

	High	Medium	Low
Contact Frequency:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Vibration Influence:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Air Erosion Potential:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Overall Rating:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Comments:

Inspector Signature:

Date

AHERA Inspector Certification #:

M. A. Rickett

13-BI-2501

9/14/12

# AHERA ASBESTOS RE-INSPECTION

## Physical Assessment Data

Building Name:	GSA Warehouse 2	Building Number:	WA0825KF
Service Center:	Northwest/Arctic Region		
Property Manager:	Michelle Leach	Telephone:	253-931-7289
Address:	2703 - C Street Southwest, Auburn, Washington		
HSA #:	271		
Functional Area / Location:	Floor 1: Throughout ducting		

### ORIGINAL AHERA INSPECTION DATA

Type of Asbestos Material:	<input type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input checked="" type="checkbox"/> Misc.	<input checked="" type="checkbox"/> Friable <input type="checkbox"/> Non Friable	<input type="checkbox"/> Not Accessible
Asbestos Material Description:	Vibration dampening cloths		
	<input type="checkbox"/> Assumed ACM <input checked="" type="checkbox"/> Laboratory Analysis	ACM %:	Quantity: 24 <input checked="" type="checkbox"/> SF <input type="checkbox"/> LF <input type="checkbox"/> EA

### RE-INSPECTION DATA

Date:	9/14/12	Change from Prior Inspection:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Sample Taken:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Amount of Asbestos Material:	24		<input type="checkbox"/> SF <input type="checkbox"/> LF <input checked="" type="checkbox"/> EA	<input checked="" type="checkbox"/> Friable <input type="checkbox"/> Non Friable	
Asbestos Material Description:	VIBRATION DAMPENING CLOTH				

### CONDITION AT THE TIME OF INSPECTION

Type of Damage:	<input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical	Location of Damage:	<input type="checkbox"/> Localized <input type="checkbox"/> Distributed
Extent of Damage:	<input checked="" type="checkbox"/> 0% <input type="checkbox"/> 1 - 10% <input type="checkbox"/> 10 - 20% <input type="checkbox"/> > 25%	Overall Rating:	<input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor
Damage Description:			

### POTENTIAL FOR DISTURBANCE

	High	Medium	Low
Contact Frequency:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Vibration Influence:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Air Erosion Potential:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Overall Rating:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

Inspector Signature:

AHERA Inspector Certification #:

Date

[Signature]  
 13-BI-2501

9/14/12

# AHERA ASBESTOS RE-INSPECTION

## Physical Assessment Data

Building Name:	GSA Warehouse 2	Building Number:	WA0825KF
Service Center:	Northwest/Arctic Region		
Property Manager:	Michelle Leach	Telephone:	253-931-7289
Address:	2703 - C Street Southwest, Auburn, Washington		
HSA #:	304A		
Functional Area / Location:	Floor 1: Office hallway, Electronics Shop, 205, 207, 209, Entry to Women and Men restrooms- See HM drawings		

### ORIGINAL AHERA INSPECTION DATA

Type of Asbestos Material:	<input type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input checked="" type="checkbox"/> Misc.	<input checked="" type="checkbox"/> Friable <input type="checkbox"/> Non Friable	<input type="checkbox"/> Not Accessible
Asbestos Material Description:	9" VAT with ACM mastic on concrete		
	<input type="checkbox"/> Assumed ACM <input checked="" type="checkbox"/> Laboratory Analysis	ACM %:	Quantity: 2,892 <input checked="" type="checkbox"/> SF <input type="checkbox"/> LF <input type="checkbox"/> EA

### RE-INSPECTION DATA

Date:	9/14/12	Change from Prior Inspection:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Sample Taken:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Amount of Asbestos Material:	2892		<input type="checkbox"/> SF <input checked="" type="checkbox"/> LF <input type="checkbox"/> EA	<input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable	
Asbestos Material Description:	9" VAT w/ ACM MASTIC				

### CONDITION AT THE TIME OF INSPECTION

Type of Damage:	<input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical	Location of Damage:	<input type="checkbox"/> Localized <input type="checkbox"/> Distributed
Extent of Damage:	<input checked="" type="checkbox"/> 0% <input type="checkbox"/> 1 - 10% <input type="checkbox"/> 10 - 20% <input type="checkbox"/> > 25%	Overall Rating:	<input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor
Damage Description:			

### POTENTIAL FOR DISTURBANCE

	High	Medium	Low
Contact Frequency:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Vibration Influence:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Air Erosion Potential:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Overall Rating:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:

Inspector Signature:

*Mandy P. [Signature]*

Date

9/14/12

AHERA Inspector Certification #:

13-BI-2501

# AHERA ASBESTOS RE-INSPECTION

## Physical Assessment Data

Building Name:	GSA Warehouse 2	Building Number:	WA0825KF
Service Center:	Northwest/Arctic Region		
Property Manager:	Michelle Leach	Telephone:	253-931-7289
Address:	2703 - C Street Southwest, Auburn, Washington		
HSA #:	304B		
Functional Area / Location:	Floor 1: Office areas, Entry to Women restroom- See HM drawings		

### ORIGINAL AHERA INSPECTION DATA

Type of Asbestos Material:	<input type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input checked="" type="checkbox"/> Misc.	<input checked="" type="checkbox"/> Friable <input type="checkbox"/> Non Friable	<input type="checkbox"/> Not Accessible
Asbestos Material Description:	Non-ACM carpet over 9" VAT with ACM mastic on concrete		
	<input type="checkbox"/> Assumed ACM <input checked="" type="checkbox"/> Laboratory Analysis	ACM %:	Quantity: 264 <input checked="" type="checkbox"/> SF <input type="checkbox"/> LF <input type="checkbox"/> EA

### RE-INSPECTION DATA

Date:	9/14/12	Change from Prior Inspection:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Sample Taken:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Amount of Asbestos Material:	264		<input checked="" type="checkbox"/> SF <input type="checkbox"/> LF <input type="checkbox"/> EA	<input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable	
Asbestos Material Description:	9" VAT & ACM MASTIC UNDER CARPET				

### CONDITION AT THE TIME OF INSPECTION

Type of Damage:	<input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical	Location of Damage:	<input type="checkbox"/> Localized <input type="checkbox"/> Distributed
Extent of Damage:	<input checked="" type="checkbox"/> 0% <input type="checkbox"/> 1 - 10% <input type="checkbox"/> 10 - 20% <input type="checkbox"/> > 25%	Overall Rating:	<input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor
Damage Description:			

### POTENTIAL FOR DISTURBANCE

	High	Medium	Low
Contact Frequency:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vibration Influence:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Air Erosion Potential:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Overall Rating:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

Inspector Signature:

AHERA Inspector Certification #:

Date

[Signature]  
 13-BI-2501

9/14/12



# AHERA ASBESTOS RE-INSPECTION

## Physical Assessment Data

Building Name:	GSA Warehouse 2	Building Number:	WA0825KF
Service Center:	Northwest/Arctic Region		
Property Manager:	Michelle Leach	Telephone:	253-931-7289
Address:	2703 - C Street Southwest, Auburn, Washington		
HSA #:	338		
Functional Area / Location:	Floor 1: Throughout		

### ORIGINAL AHERA INSPECTION DATA

Type of Asbestos Material:	<input type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input checked="" type="checkbox"/> Misc.	<input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable	<input type="checkbox"/> Not Accessible
Asbestos Material Description:	Gaskets		
	<input checked="" type="checkbox"/> Assumed ACM <input type="checkbox"/> Laboratory Analysis	ACM %:	N/A
	Quantity:	8	<input type="checkbox"/> SF <input type="checkbox"/> LF <input checked="" type="checkbox"/> EA

### RE-INSPECTION DATA

Date:	9/14/12	Change from Prior Inspection:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Sample Taken:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Amount of Asbestos Material:	8		<input type="checkbox"/> SF <input type="checkbox"/> LF <input checked="" type="checkbox"/> EA	<input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable	
Asbestos Material Description:	GASKETS				

### CONDITION AT THE TIME OF INSPECTION

Type of Damage:	<input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical	Location of Damage:	<input type="checkbox"/> Localized <input type="checkbox"/> Distributed
Extent of Damage:	<input checked="" type="checkbox"/> 0% <input type="checkbox"/> 1 - 10% <input type="checkbox"/> 10 - 20% <input type="checkbox"/> > 25%	Overall Rating:	<input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor
Damage Description:			

### POTENTIAL FOR DISTURBANCE

	High	Medium	Low
Contact Frequency:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Vibration Influence:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Air Erosion Potential:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Overall Rating:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Comments:

Inspector Signature:

*Mark A. Ruckert*

Date

9/14/12

AHERA Inspector Certification #:

13-BI-2501



# AHERA ASBESTOS RE-INSPECTION

## Physical Assessment Data

Building Name:	GSA Warehouse 2	Building Number:	WA0825KF
Service Center:	Northwest/Arctic Region		
Property Manager:	Michelle Leach	Telephone:	253-931-7289
Address:	2703 - C Street Southwest, Auburn, Washington		
HSA #:	367		
Functional Area / Location:	Floor 1: Warehouse floor Bay 1-4		

### ORIGINAL AHERA INSPECTION DATA

Type of Asbestos Material:	<input type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input checked="" type="checkbox"/> Misc.	<input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable	<input type="checkbox"/> Not Accessible
Asbestos Material Description:	Floor expansion seam caulking		
	<input type="checkbox"/> Assumed ACM <input checked="" type="checkbox"/> Laboratory Analysis	ACM %:	Quantity: 1,480 <input type="checkbox"/> SF <input checked="" type="checkbox"/> LF <input type="checkbox"/> EA

### RE-INSPECTION DATA

Date:	9/14/12	Change from Prior Inspection:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Sample Taken:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Amount of Asbestos Material:	1480		<input type="checkbox"/> SF <input checked="" type="checkbox"/> LF <input type="checkbox"/> EA	<input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable	
Asbestos Material Description:	FLOOR SEAM CAULKING				

### CONDITION AT THE TIME OF INSPECTION

Type of Damage:	<input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical	Location of Damage:	<input type="checkbox"/> Localized <input type="checkbox"/> Distributed
Extent of Damage:	<input checked="" type="checkbox"/> 0% <input type="checkbox"/> 1 - 10% <input type="checkbox"/> 10 - 20% <input type="checkbox"/> > 25%	Overall Rating:	<input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor
Damage Description:			

### POTENTIAL FOR DISTURBANCE

	High	Medium	Low
Contact Frequency:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vibration Influence:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Air Erosion Potential:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Overall Rating:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Inspector Signature: *James A. Ricketts* Date: 9/14/12

AHERA Inspector Certification #: 13-BI-2501

# AHERA ASBESTOS RE-INSPECTION

## Physical Assessment Data

Building Name:	GSA Warehouse 2	Building Number:	WA0825KF
Service Center:	Northwest/Arctic Region		
Property Manager:	Michelle Leach	Telephone:	253-931-7289
Address:	2703 - C Street Southwest, Auburn, Washington		
HSA #:	372		
Functional Area / Location:	Floor 1: Warehouse Bay 1-4 on wood joist beam at ceiling level		

### ORIGINAL AHERA INSPECTION DATA

Type of Asbestos Material:	<input checked="" type="checkbox"/> Surfacing <input type="checkbox"/> TSI <input type="checkbox"/> Misc.	<input checked="" type="checkbox"/> Friable <input type="checkbox"/> Non Friable	<input type="checkbox"/> Not Accessible
Asbestos Material Description:	Patching		
	<input checked="" type="checkbox"/> Assumed ACM <input type="checkbox"/> Laboratory Analysis	ACM %:	N/A
	Quantity:	200	<input checked="" type="checkbox"/> SF <input type="checkbox"/> LF <input type="checkbox"/> EA

### RE-INSPECTION DATA

Date:	9/14/12	Change from Prior Inspection:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Sample Taken:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Amount of Asbestos Material:	200		<input checked="" type="checkbox"/> SF <input type="checkbox"/> LF <input type="checkbox"/> EA	<input checked="" type="checkbox"/> Friable <input type="checkbox"/> Non Friable	
Asbestos Material Description:	PATCHING				

### CONDITION AT THE TIME OF INSPECTION

Type of Damage:	<input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical	Location of Damage:	<input type="checkbox"/> Localized <input type="checkbox"/> Distributed
Extent of Damage:	<input checked="" type="checkbox"/> 0% <input type="checkbox"/> 1 - 10% <input type="checkbox"/> 10 - 20% <input type="checkbox"/> > 25%	Overall Rating:	<input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor
Damage Description:			

### POTENTIAL FOR DISTURBANCE

	High	Medium	Low
Contact Frequency:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Vibration Influence:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Air Erosion Potential:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Overall Rating:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Comments:

Inspector Signature:

*Maureen Robert*

Date

9/14/12

AHERA Inspector Certification #:

13-BI-2501

# AHERA ASBESTOS RE-INSPECTION

## Physical Assessment Data

Building Name:	GSA Warehouse 2	Building Number:	WA0825KF
Service Center:	Northwest/Arctic Region		
Property Manager:	Michelle Leach	Telephone:	253-931-7289
Address:	2703 - C Street Southwest, Auburn, Washington		
HSA #:	379		
Functional Area / Location:	Throughout - See HM drawings		

### ORIGINAL AHERA INSPECTION DATA

Type of Asbestos Material:	<input type="checkbox"/> Surfacing <input checked="" type="checkbox"/> TSI <input type="checkbox"/> Misc.	<input checked="" type="checkbox"/> Friable <input type="checkbox"/> Non Friable	<input type="checkbox"/> Not Accessible
Asbestos Material Description:	TSI pipe fittings		
	<input type="checkbox"/> Assumed ACM <input checked="" type="checkbox"/> Laboratory Analysis	ACM %:	Quantity: 530 <input type="checkbox"/> SF <input type="checkbox"/> LF <input checked="" type="checkbox"/> EA

### RE-INSPECTION DATA

Date:	9/14/12	Change from Prior Inspection:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Sample Taken:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Amount of Asbestos Material:	530		<input type="checkbox"/> SF <input type="checkbox"/> LF <input checked="" type="checkbox"/> EA	<input checked="" type="checkbox"/> Friable <input type="checkbox"/> Non Friable	
Asbestos Material Description:	PIPE FITTINGS				

### CONDITION AT THE TIME OF INSPECTION

Type of Damage:	<input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical	Location of Damage:	<input type="checkbox"/> Localized <input type="checkbox"/> Distributed
Extent of Damage:	<input checked="" type="checkbox"/> 0% <input type="checkbox"/> 1 - 10% <input type="checkbox"/> 10 - 20% <input type="checkbox"/> > 25%	Overall Rating:	<input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor
Damage Description:			

### POTENTIAL FOR DISTURBANCE

	High	Medium	Low
Contact Frequency:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vibration Influence:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Air Erosion Potential:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Overall Rating:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

Inspector Signature:

AHERA Inspector Certification #:

Maurice P. Robert

13-BI-2501

Date

9/14/12

# AHERA ASBESTOS RE-INSPECTION

## Physical Assessment Data

Building Name:	GSA Warehouse 2	Building Number:	WA0825KF
Service Center:	Northwest/Arctic Region		
Property Manager:	Michelle Leach	Telephone:	253-931-7289
Address:	2703 - C Street Southwest, Auburn, Washington		
HSA #:	381		
Functional Area / Location:	Floor 1: Throughout (except boiler room) - See HM drawings		

### ORIGINAL AHERA INSPECTION DATA

Type of Asbestos Material:	<input type="checkbox"/> Surfacing <input checked="" type="checkbox"/> TSI <input type="checkbox"/> Misc.	<input type="checkbox"/> Friable <input checked="" type="checkbox"/> Non Friable	<input type="checkbox"/> Not Accessible
Asbestos Material Description:	TSI pipe insulation on runs		
	<input type="checkbox"/> Assumed ACM <input checked="" type="checkbox"/> Laboratory Analysis	ACM %:	Quantity: 2,260 <input type="checkbox"/> SF <input checked="" type="checkbox"/> LF <input type="checkbox"/> EA

### RE-INSPECTION DATA

Date:	9/14/12	Change from Prior Inspection:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Sample Taken:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Amount of Asbestos Material:	2260		<input type="checkbox"/> SF <input checked="" type="checkbox"/> LF <input type="checkbox"/> EA	<input checked="" type="checkbox"/> Friable <input type="checkbox"/> Non Friable	
Asbestos Material Description:	PIPE LAGGING				

### CONDITION AT THE TIME OF INSPECTION

Type of Damage:	<input type="checkbox"/> Deterioration <input type="checkbox"/> Water <input type="checkbox"/> Physical	Location of Damage:	<input type="checkbox"/> Localized <input type="checkbox"/> Distributed
Extent of Damage:	<input checked="" type="checkbox"/> 0% <input type="checkbox"/> 1 - 10% <input type="checkbox"/> 10 - 20% <input type="checkbox"/> > 25%	Overall Rating:	<input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor
Damage Description:			

### POTENTIAL FOR DISTURBANCE

	High	Medium	Low
Contact Frequency:	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Vibration Influence:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Air Erosion Potential:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Overall Rating:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments:

Inspector Signature:

*Mark A. Robert*

Date

9/14/12

AHERA Inspector Certification #:

13-BI-2501

## **APPENDIX C**

### **AHERA BUILDING INSPECTOR CERTIFICATION**

**I CORP AND JOINT BASE LEWIS-MCCHORD, PUBLIC WORKS ASBESTOS CERTIFICATION**

Presented By The

*Environmental and Natural Resources Division*

*Building 2012, JBLM, WA 98433 (253) 966-1776*

**MARC RICKERT**

Has successfully completed the requisite training, under TSCA Title II, EPA AHERA & ASHARA M.A.P.  
for the following discipline:

**ASBESTOS BUILDING INSPECTOR REFRESHER**

CERTIFICATION NUMBER: 13-BI-2501

INSTRUCTOR:

  
Michael C. Roberts

Certification Date: 5/17/2012

Expiration Date: 5/17/2013

State of Florida, Provider Number 3501, Course Number 6306